

Bollettino n. 25 del 19 novembre 2019

Nella giornata odierna non è stato possibile elaborare i dati del sistema fotografico. I dati riportati di seguito, pertanto, si riferiscono al sistema radar e NON al sistema fotografico.

Dati monitoraggio radar

Negli ultimi 3 giorni il settore C del Ghiacciaio di Planpincieux risulta in rallentamento in termini di velocità rispetto ai valori riportati nel bollettino precedente, facendo registrare uno spostamento medio giornaliero pari a 20 cm al giorno.

Il settore B, da 250.000 m³ stimati, risulta in rallentamento in termini di velocità rispetto ai valori riportati nel bollettino precedente, facendo registrare uno spostamento medio giornaliero pari a 15 cm al giorno.

Il settore A risulta in rallentamento in termini di velocità rispetto ai valori riportati nel bollettino precedente, facendo registrare uno spostamento medio giornaliero pari a 10 cm al giorno.

English version

Today it was not possible to process the data from the photographic monitoring system. Therefore, the following data refer to the radar monitoring system and NOT to the photographic system.

Radar monitoring data

The data from the last 3 days shows velocities decreasing for sectors A, B and C, with values equal to 10, 15 and 20 cm/d respectively.